

List of plates

Plate No.	Title	Page No.
1	Satellite imagery showing location of Narmada and Karjan dam sites and Piplod fault	3
2	Site condition prior and after the construction of the dam (view from left bank), Sardar Sarovar (Narmada) Project (a) Excavated foundation of dam (b) Partly constructed dam	5
3	Site condition prior and during the construction of stilling basin, Karjan dam (a) Basalt flows mainly covered by dumped material (b) Partly constructed stilling basin with end sill	6
4	Agglomerate and columnar jointed basalt (basal clinkery zone is absent) in the foundation of right training wall displaced by a fault, Sardar Sarovar (Narmada) Project	34
5	Sub-horizontal disposition of the infra-trappean sedimentaries (Bagh beds) and basalt flows in the Right Bank of the dam, Sardar Sarovar (Narmada) Project	35
6	Excavated trench along river channel fault, Sardar Sarovar (Narmada) Project	36
7	Exposure of ropy lava at the Karjan dam site	39
8	Disposition of weathered rock seam in the foundation of spillway block and preparation of in-situ shear test blocks, Karjan dam (a) Disposition of weathered rock seam in the foundation of dam block (b) Preparation of in-situ shear test blocks on weathered rock seam	40
9	Foundation preparation of the river channel fault exposed at the dam base (view from upstream), Karjan dam	42
10	Disposition and treatment of red bole layer at the toe of spillway Block, Sardar Sarovar (Narmada) Project (a) Disposition of red bole layer in the foundation of spillway block (b) Open concrete shear key in the foundation of spillway block	68
11	Treatment of the argillaceous sandstone layers in the Right Bank foundation of spillway blocks through shafts, Sardar Sarovar (Narmada) Project	69
12	Treatment of upper argillaceous sandstone through drift and shaft in the foundation of spillway block, Sardar Sarovar (Narmada) Project	70
13	Sub-horizontal shear exposed in the treatment drift traversing the argillaceous sandstone, Sardar Sarovar (Narmada) Project	71
14	Treatment drift for the upper argillaceous sandstone layer, Sardar Sarovar (Narmada) Project (a) Sheared tuff layer exposed in the crown of the drift (b) Colcrete in the upper (crown) part of the drift	72
15	Excavation of approach drift for the treatment of weathered rock seam in the foundation of block L-5, Karjan dam	73

16	Pump concrete in the crown of treatment drift in the foundation of spillway block, Karjan dam	74
17	Foundation treatment of block-16 and 17, Sardar Sarovar (Narmada) Project (a) Removal of weathered rock mass in part foundation of the block-16 (b) Hammock reinforced concrete in the foundation of block-16 and sloping concrete in the foundation of block-17	95
18	Disposition of red bole layer in the foundation of divide wall between Lower Chute and Stilling Basin, Sardar Sarovar (Narmada) Project	98
19	Seepage along flow contact, Sardar Sarovar (Narmada) Project	104
20	Surface manifestation of the Piplod fault (a) Straight course of Tarav Nala near Piplod (b) Near vertical disposition of infra-trappean sedimentaries (Bagh beds) adjacent to fault	110
21	Outlet portal face of the Exit Tunnels prior and after shotcreting the surface, Sardar Sarovar (Narmada) Project Rock mass condition at the outlet portal face of the tunnels (b) Shotcreted (with wire mesh) outlet portal face of the tunnels	132
22	Slaked nature of vertical dolerite dyke and sill in and around the Exit Tunnel-1, Sardar Sarovar (Narmada) Project (a) Partly slaked vertical dolerite dyke inside the tunnel (b) Slaked dolerite sill at the outlet portal site of the tunnel	133
23	Slaking of dolerite rock at the portal site of Exit Tunnel, Sardar Sarovar (Narmada) Project	134
