

LIST OF PLATES

Plate No.	Title	Page No.
I.1	Major Landslide Incidences in the Study Area	4
II.1	Physiographic Views of Himalayan Mountain Terrain	14
II.2	Use of Leica GS5 GIS-GPS data collection system for inventory of field data	28
II.3	Field Photographs of Observed Rock Types and Structures Associated with the HHC	34-35
II.4	Photomicrographs of Different Rock Types and Structures Associated with the Higher Himalayan Crystallines/Rungling Crystallines	38-39
II.5	Field Photographs of Different Rock Types and Structures Associated with SSZ	47-49
II.6	Photomicrographs of Different Rock Types and Structures Associated with Sirdang Sedimentary Zone	51-52
II.7	Rock Type Variation (CCB) and Associated Features Between Tawaghat – Gasku Segment Along Kali River Valley	55-56
II.8	Photomicrographs of Different Rock Types and Structure Associated with the Chiplakot Crystalline Rocks	58
II.9	Field Photographs Showing Field Disposition of MCT and NCT in Kali and Dauliganga Valley	63
III.1	A downstream view of Kali River segment characterized by deep gorgy, 'V' shaped valley (Loc.Mangati landslide)	67
III.2	Panoramic view of wide – open Kali River valley (Loc. D/S of Balwakot village)	67
III.3	Development of Triangular Facets in Sirdang Quartzites lenading to formation of narrow V-shaped valley (Loc. Pangla village)	67
III.4	Field photograph showing development of incised meanders and point bars (Loc. U/S of Pangla village)	67

III.5	Field Photograph of Glacial and Peri-Glacial Landform Features in the Study Area	73
III.6	Field Photographs of Fluvial Landforms in the Study Area	74
III.7	Tectonic Landform Features Along Kali River Channel	75
IV.1	Field photograph of different stages in ground survey carried out at Mangti Landslide	85
IV.2	Field photograph of different surface features mapped on Mangti Landslide	89-90
IV.3	Field photograph of some selective sites of scanline survey investigation along TJRC	104
IV.4	Chronological Depiction of open stand pipe type piezometer installation at Mangti Landslide	117-118
IV.5	Sequential Photographs of Movement Monitoring Rods Installation Procedure	123
IV.6	Sequence of field photographs monitoring the third phase of movement in Mangti Landslide between January 2003 to September 2005	126-128
VI.1	Field Photograph of Rain Gauge Placed Near Mangti Landslide	150
VI.2	Pictorial Depiction of Uncontrolled Blasting Generated Fracture Pattern along TJRC	165-166
VII.1	Snapshots of The Recommended Reinforcement Parameters for Anchors and Soil Nails-Mangti Lower Level Slide	195-196
VII.2	Snapshots of The Recommended Reinforcement Parameters for Anchors-Mangti Upper Level Slide	196-197
VIII.1	Sequential Field Photographs of Landslide Distribution in TJRC	228-233
VIII.2	Field Photographs of Masonry Brick Retaining Wall with Drains Constructed at Upper Level Mangti Landslide to Check Debris Flow	244
