

LIST OF PLATES

Plate No.	Description	Page No.
1	Close View of Kakrapar Weir Across Tapi River.	10
2	A View of Stabilized Coastal Onshore Dunal Ridge with Luxurious Vegetation.	29
3	Head Regulators of Chalthan and Bardoli Branch Canals.	118
4	A View of Soil Sampling Operation Using Soil Auger (Loc. Sanki Village).	180
5	High Water Level in a Well Located at Bagumara.	242
6	High Water Level in a Well Located at Mota.	242
7	Seepage Through Canal Structure Causing Water Ponding.	243
8	Unlined Sub minor in Chalthan Branch Canal Command Area.	243
9	Damaged Embankment Structure of Canal of Chalthan Branch Canal.	245
10	Damaged Canal Structure of Chalthan Branch Canal.	246
11	Saline Soils in Chalthan Branch Canal Command Area (Location: South of Bagumara village).	262
12	Saline Soils in Chalthan Branch Canal Command Area (Location: South of Mota village).	262
13	High Water Level in Agricultural Field.	264
14	A view of Kankra Khadi Showing Water Discharge Gathered from Over irrigation & Canal Seepage.	265