

# **CONTENTS**

## **Chapter 1**

### **Introduction**

1.1 Polymers and its classification	1
1.2 Need for polymer surface modification	2
1.3 Polymer surface modification techniques	3
1.4 What is plasma?	8
(i) Fundamental aspects of plasma physics	9
(ii) Types of collisions	11
(iii) Plasma surface modifications	13
1.5 Polymer surface properties relevance to adhesion	15
(i) Surface forces	15
(ii) Surface energy and surface tension	17
(iii) Mechanisms of adhesion	18
1.6 Review of plasma-polymer interaction	21
1.7 Concept of this thesis	27

## **Chapter 2**

### **Materials and Experimental Details**

2.1 Polymers Studied	29
2.1.0 Introduction	29
2.1.1 Polycarbonate (PC)	29
2.1.2 Polyethylene terephthalate (PET)	30

2.1.3 Polytetrafluoroethylene (PTFE)	31
2.1.4 Polyethersulfone (PES)	33
2.2 Details of Plasma Irradiation	36
2.3 Characterization Techniques	38
2.3.0 Introduction	38
2.3.1 Contact angle goniometry	38
2.3.2 Vicker's Microhardness	45
2.3.3 X-ray photoelectron spectroscopy (XPS)	52
2.3.3.1 The background of XPS	52
2.3.3.2 Instrumentation	55
2.3.3.3 Polymer surface chemical analysis	58
2.3.4 Atomic force microscopy	60
2.3.5 ATR-FTIR spectroscopy	64
2.3.5.1 Principle	64
2.3.5.2 Theory	66
2.3.5.3 Instrumentation	69

### **Chapter 3**

#### **Spectroscopic studies of polymer surfaces**

3.0 Introduction	72
3.1 XPS analysis	73
3.1.0 Introduction	73
3.1.1 XPS analysis of PC	76
3.1.2 XPS analysis of PET	80
3.1.3 XPS analysis of PTFE	83

3.1.4 XPS analysis of PES	87
3.1.5 Conclusion	89
3.2 ATR-FTIR Analysis	91
3.2.0 Introduction	91
3.2.1 ATR-FTIR analysis of PC	92
3.2.2 ATR-FTIR analysis of PET	94
3.2.3 ATR-FTIR analysis of PTFE	95
3.2.4 ATR-FTIR analysis of PES	97
3.2.5 Conclusion	98

**Chapter 4**

**Surface free energy, morphology and hardness studies of polymer surfaces**

4.0 Introduction	100
4.1 Surface free energy analysis	101
4.1.0 Introduction	101
4.1.1 Surface energy analysis of PC	102
4.1.2 Surface energy analysis of PET	105
4.1.3 Surface energy analysis of PTFE	107
4.1.4 Surface energy analysis of PES	110
4.1.5 Conclusion	113
4.2 Vicker's Microhardness	115
4.2.0 Introduction	115
4.2.1 Microhardness of PC films	116
4.2.2 Microhardness of PET films	117
4.2.3 Microhardness of PTFE films	119

4.2.4 Microhardness of PES films	121
4.2.5 Conclusion	122
4.3 Atomic Force Microscopy analysis	123
4.3.0 Introduction	123
4.3.1 AFM Analysis of PC films	123
4.3.2 AFM Analysis of PET films	125
4.3.3 AFM Analysis of PTFE films	126
4.3.4 AFM Analysis of PES films	127
4.3.5 Summary and Conclusion	129
<b>Chapter 5</b> Summary and Conclusions with future perspective	131
<b>REFERENCES</b>	139