List of Figures and Tables

Chapter 1

Figure.1.1: Schematic diagram of the state transition processes	. 9
Figure 1.2: Mechanism of adhesion : Mechanical interlocking	18
Figure 1.3: Mechanism of adhesion : Interdiffusion of chains	19
Figure 1.4: Mechanism of adhesion : Electrical interactions	19
Figure 1.5 : Mechanism of adhesion: Chemical interactions (adsorption theory)	20
Chapter 2	
Figure 2.1: Illustration of polymerization of tetrafluoroethylene into PTFE	32
Table 2.1: Some of the physical and chemical properties of thepolymers used	35
Figure 2.2: Schematic of the experimental set-up	37
Figure 2.3: Voltage and current waveform	37
Figure 2.4: Contact angle goniometer (NRL C.A. Goniometer, Model 100-00-230)	39
Figure 2.5 : a) Non-wetting of solid surface ($\theta > \pi/2$), b) Partial wetting of solid surface ($\theta < \pi/2$) and c) Complete wetting of solid surface ($\theta = 0$)	41
Figure 2.6: Zisman plot for estimating surface tension of liquid	43
Figure 2.7: Vicker's Microhardness Indenter Future Tech. (FM-700)	46
Figure 2.8 : Schematic illustration of indentation load-displacement data showing important measured parameters	47
Figure 2.9: Schematic illustration of the unloading process showing parameters characterizing the contact geometry	49
Figure 2.10: Photoemission and subsequent relaxation processes, XRF and AES	53

Figure 2.12: General principle of AFM 60
Figure 2.13: ATR-FTIR Spectrometer 64
Rigure 2.14: A multiple reflection ATR system65
Figure 2.15: Normal modes of CO_2 molecule. The arrows indicate 68 he direction of motion of atoms at a particular instant. Later on the lirections are reversed.
Figure 2.16: Normal modes of H_2O molecule. The arrows indicate 68 he direction of motion of atoms at a particular instant. Later on the directions are reversed.
Cable 2.2 : Some of the important bonds69
Chapter 3
Figure 3.1 : The structure of the PC bisphenol-A with numbered 76 carbon bonds: 1-phenyl ring (p.r), 2-C-C, C-H, 3-C-(phenyl ring), 4- D-(C=O)-O
Figure 3.2: XPS spectra of (a) C 1s peak of untreated PC sample; (b) 77 C 1s peak of Ar Plasma treated PC sample; (c) O 1s peak of untreated PC sample; (d) O 1s peak of Ar Plasma treated PC sample. The number corresponds to bond according to Figure 3.1
Fable 3.1: Binding energy and the relative areas of individual peaks78numbered according to Figure 3.1. The areas were normalized to thefirst peak area
Fable 3.2: Atomic concentration of carbon and oxygen measured by79KPS for untreated and argon plasma treated (10 mins) PC
Figure 3.3: The structure of the PET: A: C-C bonds in phenyl ring; 80 3: C-O; C: $O=C-O$
Figure 3.4 : XPS spectra of (a) C 1s peak of untreated PET sample; 81 b) C 1s peak of Ar Plasma treated PET sample; (c) O 1s peak of untreated PET sample; (d) O 1s peak of Ar Plasma treated PET sample. The alphabets A, B and C corresponds to bond according to Figure 3.3
Figure 5.5

XPS for untreated and plasma treated (10 min) sample	0.
Table 3.4 : Atomic concentration of carbon and oxygen measured byXPS for untreated and plasma treated (10 min) sample	8.
Figure 3.5: XPS spectra of (a): C 1s untreated; (b): C 1s argon plasma treated; (c): O 1s untreated; (d): O 1s argon plasma treated; (e): F 1s Untreated; (f): F 1s argon plasma treated	8
Table 3.5: Binding energy and the areas of individual peaks	8
Table 3.6 : The surface composition of PTFE before and after the plasma treatment	80
Table 3.7: Binding energy and the areas of individual peaks	8
Figure 3.6: C 1s peak of the XPS spectra of (a) untreated and (b) Ar plasma treated samples; O 1s peak of the XPS spectra of (c) untreated and (d) Ar plasma treated samples	8
Table 3.8: The surface composition of PES before and after the plasma treatment	8
Table 3.9: Surface composition before and after the plasma treatment	. 9
Figure 3.7 : ATR-FTIR spectra for pristine and argon plasma treated PC samples	9
Figure 3.8 : <i>ATR-FTIR spectra for pristine and argon plasma treated</i> <i>PET samples</i>	. 9
Figure 3.9 : ATR-FTIR spectra for pristine and argon plasma treated PTFE samples	9
Figure 3.10: ATR-FTIR spectra for pristine and irradiated PES samples	9
Chapter 4	
Table 4.1: Surface free energy and its polar and dispersioncomponents of water and glycerin used to determine the surface freeenergy	10
Table 4.2: Contact angles for untreated and argon plasma treated PC samples	10

Figure 4.1 : Comparison of Surface free energy and its components before and after the treatment in Ar discharge	102
Table 4.3: Comparison of surface free energy and its components before and after Ar plasma treatment	103
Table 4.4: SFE values for argon plasma treated PC samples with respect to untreated PC sample	104
Table 4.5: Contact angles for untreated and argon plasma treatedPET samples	105
Figure 4.2 : Comparison of Surface free energy and its components before and after the treatment in <i>Ar</i> discharge	105
Table 4.6: Comparison of surface free energy and its components before and after Ar plasma treatment	106
Table 4.7 : SFE values for argon plasma treated PET samples with respect to untreated PET sample	107
Table 4.8: Contact angles for untreated and argon plasma treatedPTFE samples	108
Figure 4.3: Comparison of Surface free energy and its components before and after the treatment in Ar discharge	108
Table 4.9 : Comparison of surface free energy and its components before and after Ar plasma treatment	109
Table 4.10 : SFE values for argon plasma treated PTFE samples with respect to untreated PTFE sample	110
Table 4.11: Contact angles for untreated and argon plasma treated PES samples	110
Table 4.12: Comparison of surface free energy and its components before and after Ar plasma treatment	111
Figure 4.4: Comparison of Surface free energy and its components before and after the treatment in Ar discharge	112
Table 4.13: SFE values for argon plasma treated PES samples with respect to untreated PES sample	112
Table 4.14: Polar components of surface energy	113

.

Figure 4.5: Indentation Marks on polymer surface	. 11
Figure 4.6: Plot of hardness vs applied loads	11
Table 4.15 : Hv values of argon plasma treated PC polymer with change in load	11
Figure 4.7: Plot of hardness vs applied loads	. 11
Table 4.16: Hv values of argon plasma treated PET polymer with change in load	11
Figure 4.8: Plot of hardness vs applied loads	12
Table 4.17 : Hv values of argon plasma treated PTFE polymer with change in load	12
Figure 4.9: Plot of hardness vs applied loads	12
Table 4.18: Hv values of argon plasma treated PES polymer with change in load	12
Figure 4.10 : AFM photomicrographs of (a) untreated PC film, (b) Ar plasma treated PC for 5 min, (c) Ar plasma treated PC for 10 min, (d) Ar plasma treated PC for 50 min	12
Figure 4.11: AFM photomicrographs of (a) untreated PET film, (b) Ar plasma treated PET for 5 min, (c) Ar plasma treated PET for 10 min, (d) Ar plasma treated PET for 50 min	12
Figure 4.12: AFM photomicrographs of (a) untreated PTFE film, (b) Ar plasma treated PTFE for 5 min, (c) Ar plasma treated PTFE for 10 min, (d) Ar plasma treated PTFE for 50 min	12
Figure 4.13: AFM photomicrographs of (a) untreated PES film, (b) Ar plasma treated PES for 5 min, (c) Ar plasma treated PES for 10 min, (d) Ar plasma treated PES for 50 min	12
Table 4.19: The root mean square (RMS) surface roughness of argon ion irradiated polymers	12
Chapter 5	
Figure 5.1: O/C ratios for the studied polymers	13
Table 5.1: Change in SFE for untreated and argon plasma treated	13

samples

 Table 5.2: RMS values for untreated and argon plasma treated samples

,