

## **LIST OF TABLES**

<b>Table No.</b>	<b>Title</b>	<b>Page No.</b>
2.1	Industrial sources of heavy metals	7
2.2	Benefits of recycling	9
2.3	Sources of heavy metal in industrial waste and their side effects	11
2.4	Treatment techniques for recovery of heavy metals	16
2.5	Metal cationic extractants	21
2.6	Metal anion extractants	24
2.7	Solvating extractants	25
2.8	Recovery of heavy metals from industrial waste water using solvent extraction	28
3.1	Extractants properties	44
3.2	Optimized parameters for AAS analysis of metals	46
3.3	Compilation of characterization techniques	50
4.1	Applications of brass	52
4.2	Recovery of copper and zinc from brass components/pickle liquors	54
4.3	Composition of brass pickle liquor	67
4.4	Equilibrium constants of formation reactions of copper oxalate and zinc oxalate complexes	80
4.5	Stage wise recovery of copper and zinc	85
5.1	Advantages and disadvantages of etchants used during PCB etching process	112
5.2	Recovery methods for etching solutions and their operating parameters	115
5.3	Composition of spent printed circuit board etchant	118

5.4	Stage wise recovery of copper	126
5.5	Key solution properties of Strippants	127
5.6	Crystallite size and lattice parameters for copper oxalate	131
5.7	Synthesis of aniline from nitrobenzene	144
6.1	Oxalates prepared using PS technique and effect of parametric variations	161
6.2	Composition of brass rinse liquor	163
6.3	Statistical distribution of copper oxalate particles: Effect of RPM and time	169
6.4	Statistical distribution of zinc oxalate particles: Effect of RPM and time	171
6.5	Effect of oxalic acid concentration on copper recovery	172
6.6	Effect of oxalic acid concentration on zinc recovery	174
6.7	Statistical distribution of copper oxalate particles: Effect of oxalic acid concentration	175
6.8	Statistical distribution of zinc oxalate particles: Effect of oxalic acid concentration	176