

Location of Bore wells

Bore well number	Location	Bore well number	Location
1.	Jasdan	24.	Padariya
2.	Adhia	25.	Hariyasan
3.	Jivapar	26.	Pipardi
4.	Chitravav (Ram)	27.	Gundasari
5.	Derdi	28.	Chavandi
6.	Sultanpur	29.	Arni
7.	Vachara	30.	Khajuda
8.	Ardoi	31.	Supedi
9.	Dholra	32.	Moti vavdi
10.	Khamba	33.	Vadla
11.	Biliyali	34.	Moti marad
12.	Bandra	35.	Nani marad
13.	Gomta	36.	Patanvav
14.	Virpur	37.	Varjang
15.	Amarnagar	38.	Satvadi
16.	Bordi samdhala	39.	Rabarika
17.	Devki Galol	40.	Kutyana
18.	Kharachiya	41.	Chitravad
19.	Pipaliya	42.	Anida vachhara
20.	Nani Parabdi	43.	Kharachiya
21.	Betavad	44.	Bhayavadar
21.a	Tarkasar	45.	Moti vavdi
22.	Rampar	46.	Jam kandorna
23.	Jasapar		