

Contents

1. INTRODUCTION	1
1.1 Background	1
1.1.1 Weathering and Biodeterioration.....	3
1.2 Substratum material in biodeterioration of the monuments	4
1.2.1 Physical properties of the substratum material.....	4
1.2.2 Chemical properties of the substratum material	4
1.3 Role of Cyanobacteria and lower plants in biodeterioration.....	5
1.3.1 Cyanobacteria and micro green algae.....	5
1.3.1.1 Cyanobacteria	6
1.3.1.2 Micro green algae	6
1.3.1.3 Biofilm formation and Extracellular polysaccharides substances (EPS).....	6
1.3.2 Bryophytes.....	7
1.3.2.2 Mineral uptake as Calcium uptake.....	8
1.3.3. Lichens.....	8
1.3.3.2 Lichen secondary metabolites and acid harmful to the substrate	9
1.4 Control measures.....	10
1.4.1 Physical treatment.....	10
1.4.2 Mechanical treatment	10
1.4.3 Chemical treatment.....	10
1.5 Rationale of the study.....	10
1.6 Objectives for present study	11
2. REVIEW OF LITERATURE	12
2.1 Cyanobacteria.....	13
2.1.1 Global Status.....	14
2.1.1.1 Culturing	14
2.1.1.2 Traditional method for identification.....	15
2.1.1.3 Identification by 16S rRNA	16
2.1.1.4 Exopolysaccharides characterization	16
2.1.1.5 Biodeterioration study.....	17

2.1.2 National status	17
2.1.2.1 Culturing and study of biodeterioration on monuments	17
2.1.2.2 Identification by Traditional method	19
2.1.2.3 Identification by 16 S rRNA gene sequences	19
2.1.2.4 Exopolysaccharides characterization	19
2.1.3 Gujarat status	20
2.1.3.1 Culturing	20
2.2.3.2 Culturing and Identification by 16S rRNA gene sequences	20
2.2.3.3 Broad characterization of Exopolysaccharides	20
2.2 Bryophytes	21
2.2.1 Global status	22
2.2.1.1 Enumeration the bryophytes on monuments.....	22
2.2.1.2 Biodeterioration study.....	22
2.2.2 National status	24
2.2.2.1 Enumeration the bryophytes on the monuments of India	24
2.2.2.2 Biodeterioration	25
2.2.3 Gujarat Status	25
2.3 Lichens	26
2.3.1 Global status	26
2.3.1.1 Enumeration of Lichens.....	26
2.3.1.2 Biodeterioration study.....	27
2.3.2 National status	28
2.3.2.1 Enumeration of Lichens.....	28
2.3.2.2 Biodeterioration study.....	30
3. STUDY AREA	32
3.1 The Champaner-Pavagadh Complex.....	33
3.1.1 Makai Kothar.....	35
3.1.2 Navlakha Kothar.....	36
3.1.3 Jain temple.....	36
3.1.4 Champaner fort	36

3.1.4.1 Saher ki Masjid	36
3.1.4.2 Mandavi	37
3.1.5 Amir Manzil	37
3.1.6. Geology	37
3.1.7 Climate.....	38
3.2 Buildings of the main campus of the Maharaja Sayajirao University of Baroda.....	38
3.2.1 Arts faculty building dome	40
3.2.2 D. N. Hall.....	41
3.2.3 Geology	41
3.2.4 Climate.....	41
4. MATERIALS AND METHODS.....	43
4.1 Site Selection.....	43
4.2 Enumeration and Identification of Biofoulants on specific geological substrata.....	45
4.2.1 Field study	45
4.2.1.1 Field Photography	46
4.2.1.2 Sample collection.....	46
4.2.1.2.1 Cyanobacteria.....	46
4.2.1.2.2 Bryophytes	47
4.2.1.2.3 Lichen.....	48
4.2.1.3 Metadata collection.....	48
4.2.2 Lab study	49
4.2.2.1 Cyanobacteria	49
4.2.2.1.1 Cyanobacteria Culture.....	49
4.2.2.1.1.2 Growth media	50
4.2.2.1.1.3 Sterilization.....	51
4.2.2.1.1.4 Culture conditions.....	51
4.2.2.1.2. Optimization of media components	52
4.2.2.1.2.1. Experimental design for optimization	52
4.2.2.1.3. Molecular identification	53
4.2.2.2. Bryophytes	56
4.2.2.2.1. Processing of collected samples.....	56

4.2.2.2.2. Isolation and photography	56
4.2.2.2.3. Morphology and Micro-morphology analysis.....	56
4.2.2.2.4. Photography of micro-morphological features	57
4.2.2.2.5. Identification of specimens and their confirmation.....	57
4.2.2.2.6. Preparation of Herbarium specimens	57
4.2.2.3. Lichen	57
4.2.2.3.1. Morphology and micromorphology analysis	57
4.2.2.3.2. Photography of micro morphological features.....	58
4.2.2.3.3. Identification of specimens and their confirmation.....	58
4.2.2.4. Geological investigation	58
4.2.2.4.1. Sample preparation for Microscopy	58
4.2.2.4.2 XRD analysis of substrate sample.....	59
4.3 To study the specific role of cyanobacteria, lichen and bryophytes in biodeterioration.	60
4.3.1 Cyanobacteria	61
4.3.1.1 Confirmation of EPS production	61
4.3.1.2 Extraction of EPS.....	62
4.3.1.3 Confirmation test of total carbohydrate	62
4.3.1.4 Acid hydrolysis	63
4.3.1.5 Determination of monosaccharides by HPTLC analysis	63
4.3.2 Bryophytes.....	64
4.3.2.1 Analysis of Calcium from apoplast regions.....	64
4.3.3 Lichen	65
4.3.3.1 Chemical colour spot test.....	65
4.3.3.2 Literature survey for knowing the presence of acids	66
4.4 To devise measures for the control of biodeteriogens.....	66
4.4.1 Selection of chemicals and site for <i>in vivo</i> study.....	67
4.4.2 Selection of specific locations on the selected site.....	67
4.4.3 Chemical preparation for experiment	68
4.4.4 Work plan for chemical conservation on site	68
5. RESULTS AND DISCUSSION	70

5.1 Identification of the diversity of the biofouling lower plants and cyanobacteria with their specific substratum.....	70
5.1.1 Cyanobacteria and Microalgae	70
5.1.1.1 Culturing and optimization	70
5.1.1.2 ANOVA for Response surface model.....	73
5.1.1.3 Coefficient estimation for model	74
5.1.1.4 Molecular study by 16S rRNA marker	75
5.1.1.5 Account wise cyanobacteria and microalgae species	77
5.1.1.6 Status of cyanobacteria and green microalgae on monuments	80
5.1.2 Bryophyte	80
5.1.2.1 Characteristic features of reported Bryophytes species	82
5.1.2.2 Status of Bryophytes on the monuments	86
5.1.3 Lichen	86
5.1.3.1 Characteristics of Lichens.....	88
5.1.3.2 Status of Lichens on monuments	90
5.1.4 Geological Investigation.....	90
5.1.4.1 Thin section of rock samples	91
5.1.4.2 XRD analysis of rock samples.....	94
5.1.4.3 Biofoulants with specific substratum.....	96
5.1.4.4 Status of Biofoulants on different substrates	98
5.1.4.4.1 Cyanobacteria and green microalgae	98
5.1.4.4.2 Bryophytes	98
5.1.4.4.3 Lichens	99
5.2 Role of specific cyanobacteria, lichen and bryophytes in biodeterioration	99
5.2.1 Cyanobacteria	99
5.2.1.1 Extraction of EPS, its Confirmatory test and Acid hydrolysis	99
5.2.1.2 Determination of monosaccharides by HPTLC analysis	100
5.2.1.3 Status of Exopolysaccharides study.....	103
5.2.2 Bryophytes.....	105
5.2.2.1 Analysis of Calcium uptake from apoplast regions (intercellular level)	105
5.2.2.2 Status of calcium Uptake study in bryophytes.....	106

5.2.3 Lichen	107
5.2.3.1 Secondary metabolites based on chemical spot test and literature	107
5.1.3 Measures for controlling the biodeteriogens	108
5.1.3.1 Outcome based on the directions	110
5.1.3.2 Outcome based on the treatments	110
5.2.4 Status of Control Measures study	111
6.CONCLUSIONS.....	113
7. BIBLIOGRAPHY	117
PUBLICATIONS.....	134