

List of figures

Figure No.	Title	Page No.
1	Location plan of Sardar Sarovar (Narmada) and Karjan dams	2
2	Geology around Sardar Sarovar (Narmada) Dam and Karjan Dam sites	4
3	Geological longitudinal section of Narmada spillway blocks	8
4	Description of Narmada and Karjan dam River Channel Fault Zones I. Mostly unhealed (HL 4-5, RMR 11) Narmada River Channel fault zone at Narmada dam base. II. Mostly healed (HL 1-2, RMR 48) Karjan River fault at Karjan dam base.	19
5	Prediction of in-situ deformation modulus E_m from rock mass classification (After Hoek et. al. 1997)	28
6	Different types of weathered rock seams in the foundation of Karjan dam	41
7	Specific gravity and water absorption of the foundation rocks, Sardar Sarovar (Narmada) Project	45
8	Ultrasonic velocity and compressive strength of foundation rocks, Sardar Sarovar (Narmada) Project (a) Ultrasonic velocity of foundation rocks (b) Compressive strength of foundation rocks	46
9	Modulus of elasticity (dynamic) and in-situ deformation of modulus of rock mass, Sardar Sarovar (Narmada) Project (a) Modulus of elasticity dynamic (b) Modulus of deformation of rock mass	47
10	In-situ deformability of sheared and jointed foundation rocks, shear zone/ fault zone, Sardar Sarovar (Narmada) Project (a) Modulus of deformation and modulus of elasticity of foundation rocks (b) Ratio of modulus of elasticity and deformation of foundation rocks	49
11	Rock Quality Designation, Compressive strength and Rock Mass Rating of main dam foundation rocks, Sardar Sarovar (Narmada) Project	50
12	Shear parameters of chlorite coated joints in the dolerite rock based on the laboratory tests, Sardar Sarovar (Narmada) Project	53
13	Physical properties of foundation rocks, Karjan dam	54
14	Compressive, tensile strength and rock mass rating of foundation rocks, Karjan dam	55
15	Plot of in-situ shear tests on weathered rock seams at Karjan dam foundation	56
16	Rock Quality Designation (RQD), Unconfined Compressive Strength and Rock Mass Rating of underground powerhouse, Sardar Sarovar (Narmada) Project	65
17	Treatment of red bole layer in the foundation of Narmada dam	66

	left bank spillway block I. Geological cross-section of spillway block showing treatment of red bole layer II. Foundation plan of treatment drifts	
18	Geological section of spillway block showing treatment of argillaceous sandstone layers at Narmada dam	67
19	Geological sections of Karjan dam showing foundation condition I. Longitudinal geological section of dam II. Critical geological abutment conditions	78
20	Treatment of Weathered rock seams in the foundation of Karjan dam spillway block I. Geological cross-section of spillway block II. Foundation plan of treatment drifts	81
21	Rock mass characteristics and treatment of Narmada river channel fault at the dam base I. Treatment of fault zone II. Rock mass rating and modulus properties of fault zone and adjacent rocks	87
22	Foundation treatment of weathered rock in the foundation of block- 16 & 17 I. Cross-section of block-16 II. Longitudinal section of block-16 & 17	97
23	Typical section of Narmada dam left divide wall block-28 showing foundation treatment of scoured rock	99
24	Geological section of Karjan dam spillway block showing disposition of pinching and swelling type weathered rock seam	101
25	Longitudinal geological section of Left Non Over Flow block showing disposition of weathered rock seam	102
26	Geological section (at Chainage 1275m) of Narmada dam foundation showing tracer study holes and permeability results of limestone rock	105
27	Post grouting seepage and additional curtain grouting of the foundation of spillway blocks, Karjan dam	108
28	Geology and layout of underground powerhouse	113
29	Geological section of machine hall, Sardar Sarovar (Narmada) Project I. Geological cross-section of machine hall II. Geological section of the machine hall	114
30	Plan and section of machine hall of underground powerhouse showing disposition of cracks in the Pressure shafts and Bus galleries I. Plan of machine hall II. Cross-section of machine hall	116
31	Rock mass characteristics and disposition of shear zones in the machine hall	119
32	Geological map of part of machine hall showing disposition of major discontinuities I. 3-D Geological map of part of the machine hall II. Geological cross-section of machine hall	120
33	Plot of 3-DEC (3-Dimensional Distinct Element Code) Discontinuum analysis model study results of downstream wall of Powerhouse cavern (Machine hall) prior to the excavation of ramp I. Minor Principal Stress Contour (A-F) Plan at El.20m,	123

	II. Plan showing cracks as observed in the model studies at El. 20m and III. Section of the downstream wall showing cracks as observed in the model studies at 5m distance from the outer face of the wall.	
34	Plot of rock bolt and cable lengths for roof (arch) and side wall support of underground powerhouse cavern I. Roof support II. Wall support	127
35	Geological conditions of water conductor system of underground powerhouse I. Geological cross-section of part of draft tube tunnel-2 showing over-break II. Geological section along water conductor system	130
